APPROACH FOR SAFE TRANSPORT OF THE SAMPLE INCLUDING NUCLEAR MATERIAL

T.Yamashita(1), K. Morita(1), K. Taniguchi(1)

(1) Transnuclear, LTD Transport & Maintenance Department

Outline

• Certified Reference Material (hereafter called as to CRM) is indispensable for Quality Assurance and Material Accountability in nuclear fuel plants.

P

- CRM whose radioactivity is low is transported as Excepted package or Type A package with non fissile or fissile-excepted.
- The package is shipped and transported after the consignor check the conformity to the technical requirement of transport regulation.

Q

• It is important to ensure the conformity to the technical requirement of transport regulation.

Package — Classification —

Item	Excepted package	IP-1 package	IP-2 package	IP-3 package	Type A package	Type B package
Technical requirement	Yes	Yes	Yes	Yes	Yes	Yes
Test of normal condition of transport	No	No	Yes	Yes	Yes	Yes
Test of accident condition of transport	No	No	No	No	No	Yes
Design approval of competent authority	No	No	No	No	No	Yes
Package approval of competent authority	No	No	No	No	No	Yes
Approval of transport	No	No	No	No	No	Yes

Package — Content : Radioactivity limitation —

CRM is packed in the package

to keep the activity limit.

Excepted package	< 10-3 A2 value (Solid)
	< 10-4 A2 value (Liquid)
Type A package	<pre>< A2 value (Solid, Liquid)</pre>

to satisfy Exceptions from the requirements for packages containing fissile material.

< 15g of fissile material

Package - Content : CRM -




U : around 50mg / unit Pu : around 2mg / unit → around 0.005 A2 value / unit



Transport - Transport mode --

Transport mode	rt mode Amount of transport		Carrier	Transport route	Remarks	
	Small	Large				
Air transport	Transport cost isn't expensive. It is suitable for the small number of transport times.	In a case there is a direction about amount limit of nuclear fuel material per flight, more severer than transport regulation, the amount of CRM (nuclear fuel material) is divided, it comes to more than one transport.	•	Transport route for Class 7 cargo is the same as for general cargo.	For transport of CRM, when the amount is small, and prepared as excepted package or Type A package with fissile-excepted, there will be a merit.	
Sea transport	Transport cost is expensive. It isn't suitable for the small number of transport times.	Amount limit of nuclear fuel material per vessel complys with transport regulation. large amount of nuclear fuel material is transportrted in one transport.	Shipping company to accept nuclear fuel material is limited.	There is a case transport rute for Class 7 cargo isn't the same as for general cargo.	For transport of CRM, when the amount is large, and prepared as Type B package to come to one transport, there will be a merit.	

Transport — Transport route —



Red : Sea transport route

Confirmation of conformity to transport regulation

	Stage	Main contents of checking	
1	At the start of the transport job	Confirmation of Transport regulation for Materials (i.e. Characteristic of materials, A2 value calculation)	
2	Before the shipment from consignor	Confirmation of materials (i.e. Certificate of CRM)	
3	Departure from consignor	Confirmation of package (i.e. Label, Seal, etc.)	
4	Departure from NRT airport	Confirmation of package (i.e. Label, Seal, etc.)	
5	During the surface transport in Japan	Condition of package (i.e. Lashing condition)	
6	Arrival at consignee	Confirmation of package (i.e. Label, Seal, etc.)	

Confirmation of conformity to transport regulation — At the start of transport job —

Items	Purpose		
Material composition of CRM provided	For checking the A2 value		
Weight of CRM	For checking the A2 value		
CRM has no Be and Deuterium	For checking that CRM is fissile-excepted material		
CRM is non spontaneous combustibility material	For checking that CRM is non spontaneous combustibility material		
No dangerousness of toxic gas generate from CRM	For checking that CRM has no dangerousness of poison gas		
CRM is non-irradiated material	For checking that CRM is non-PP category material		

Check for content

Confirmation of conformity to transport regulation — Before the shipment from consignor —

Items	Purpose	
Table to show shipment No. sample No. CRM weight, package No.	For making the transport document	
Certificate of CRM	For use of CRM	

↓ Transport document ↓ Green light for shipment and transport

Confirmation of conformity to transport regulation — Departure from consignor —

Items	Purpose
One picture showing the seal and label of identification number of package	For checking the sealing For checking TNB169 is used (Type A package technical criteria)
One close-up picture showing that the wire properly goes through the holes for sealing	For checking the sealing
To confirm nothing is inside the package except for the document describing the radioactive material	For checking nothing is inside the package except for the document describing the radioactive material
The result of surface contamination for package	For checking the following value Alpha: <0.4Bq/cm2 Beta & Gamma: <4Bq/cm2
The result of radiation dose rate for package	For checking the following value At the surface: $<5 \mu$ Sv/h At 1m distance: $<0.5 \mu$ Sv/h
2 x White-I (or Yellow-II) label is put onto package	For checking the label
"Type A" label is put onto package	For checking the label
Shipper's & Consignee's name and address is put onto package	For checking the label
"UN2915" is put onto package	For checking the label
"RADIOACTIVE MATERIAL TYPE A PACKAGE" is put onto package	For checking the label
"医薬用外劇物" label is put onto package	For checking the label
Inner PE bottle and Inner can is used and its lid is closed	For checking the package technical criteria

Not to be against transport regulation

Confirmation of conformity to transport regulation — Check sheet : Departure from NRT airport—

			Rev.0
LSDスパイク用		成日	田空港出発前
2	、令に係る確認手順書(その11-	IRMM分)チェックシート 【輸送物(1/2)】	
該当法令	確認項目	技術上の確認方法	確認のチェック
·運搬則 第五条 第一項 第一号 ① •運搬則 第四条 第一号)	使用する輸送容器が容易に、かつ、安全に取 扱うことができること。		Q · 否
運搬則 第五条 第一項 第一号 ② ト運搬則 第四条 第二号)	使用する輸送容器が運搬中に予想される温 度及び内圧の変化、振動等により、き裂、破 損等の生じるおそれがないこと。		良 · 否
運搬則 第五条 第一項 第一号 ③ 1連搬則 第四条 第三号)	使用する輸送容器の表面に不要な突起物が なく、かつ、表面の汚染の除去が容易である こと。		皮 · 否
·運搬則 第五条 第一項 第一号 ④ •運搬則 第四条 第四号)	使用する輸送容器は材料相互の間及び材料 と収納される核燃料物質等との間で危険な物 理的作用又は化学反応の生じるおそれがな いこと。		
運搬則 第五条 第一項 第一号 ⑤ ▶運搬則 第四条 第五項)	使用する輸送容器の弁が誤つて操作されな いような措置が請じられていること。	輸送物表示内のTNB169(TYPEA)の文字を目視確認する。	()· 否
運搬則 第五条 第一項 第二号	使用する輸送容器の外接する直方体の各辺 が十センチメートル以上であること。		包・ 否
運搬則 第五条 第一項 第四号	使用する輸送容器の構成部品に摂氏零下四 十度から摂氏セ十度までの温度の範囲にお いて、き裂、破損等の生じるおそれはないこ と。		良・否
運搬則 第五条 第一項 第五号	使用する輸送容器が周囲の圧力を大十キロ バスカルとした場合に、放射性物質の漏えい がないこと。		し、否
運搬則 第五条 第一項 第十号 運搬則告示 第十三条	使用される輸送容器が一般の試験条件及び 液体状又は気体状で収納されているA型輸送 物に係る追加の試験条件を満足すること。		良否
核車両規則 第九条 第二項 第一号 名称及び住所並びに	輸送物に荷送人若しくは荷受人の氏名又は 名称及び住所並びに当該核燃料物質等に係 る告示で定める国連番号「UN2915」が表示さ	輸送物に輸送計画書に記載されている荷送人若しくは荷受 人の氏名又は名称及び住所が表示されていることを目視確 認する。	∯· क
주변 리가 꾀되 지?~ 개 역	も二人にのも高速量子のにおりがながられていること。	輸送物に告示で定める国連番号「UN2915」が表示されている ことを目視確認する。	良. 否
:車両規則 第九条 第二項 第二号 :車両告示 第四条の二 第二項	輸送物に当該核燃料物質等の告示で定める 品名が表示されていること。	輸送物に告示で定める品名「RADIOACTIVE MATERIAL, TYPE A PACKAGE」が表示されていることを目視確認する。	le)· 否
軍両規則 第九条 第二項 第四号	「A型」の文字又は「TYPE A」の文字が表示 されていること。	輸送物に「A型」の文字又は「TYPE A」の文字が表示されて いることを目視確認する。	③ ·否
車両規則 第九条 第二項 第十号 車両告示 第四条の二 第三項	TNB169容器は承認容器登録番号が定めら れていないため、輸送容器の設計された国の 名称及び製造業者名を表示していること。	輸送物に輸送容器の設計された国の名称及び製造業者名が 表示されていることを目視確認する。(TNB169容器の場合に は設計された国の名称(BELGUM)及び製造業社名 (TRANSNUBEL)を表示していること)	() . 否
劇法 第十二条 第一項	輸送物及び保護容器に「医薬用外劇物」の表 示がされていること	輸送物に白地に赤色の文字で「医薬用外劇物」が表示されて いることを目視により確認する。	良・否
ng 2 回目輸送	_	確認場所:	成田空港
容器の型式:TN B 1 6 9	<u>-</u>	確認日:	2609年7月6日12:19
器番号:04/033		確認者:	我田主一



Check for the conformity to transport regulation, again

Confirmation of conformity to transport regulation — Check sheet : During the surface transport —

			Rev.0		
LSDスパイク用			陸上輸送時		
	法令に係る確認手順書(その11-IRMM分)チェックシート			
該当法令	確認項目	技術上の確認方法	確認のチェック		
核軍両規則 第十六条	禄載車が駐車する際に見張人を配置してい ることを確認する。	現載車が駐車する際に見張人を記載していることを目明確認 する。	良. 否		
		積載車が駐車した際に、積載車の両側面及び後面に車面構 第(第七号棟式)が付されていることを目視確認する。			00_
				Escort car	Vehicle
		積載車の駐車地点の名称を記入すること 大栄PA	(1) · 否		
•		日本通運水戸支店到着時			
核車両規則 第十二条 第一項 核車両告示 第十条	車両標識(第七号様式)が積載車の両側面及 び後面に付されていること。	٤		Driver	Driver
		日本通運水戸支店出発時	良· 否		
		安達太良SA	良 · 否	Driver	Driver
		長者原SA	良 . 否	Operator	
			J. 否	-	
		折爪SA	良 . 否	Radiation surveyor	
				Coordinator	
核車両規則 第十二条 第三項	夜間運搬中に赤色灯を点灯すること。	夜間運搬時に赤色灯が点灯していることを目視確認する。	良・否		
					Transport caravan
					-
					Ļ
		第 2	回目輸送		
		確認場所:	各駐車地点	Check for the lasl	hing between package and vehicle
		確認日:	2009年7月6日7月		
		確認者:	よ田山康町		
	·				

Confirmation of conformity to transport regulation — Check sheet : Arrival at consignee —

LSDスパイク用		取	卸場所到着時
	法令に係る確認手順書(その11	1-IRMM分)チェックシート 【輸送物】	
該当法令	確認項目	技術上の確認方法	確認のチェック
核車面規則 第九条 第二項 第一号	輸送物に荷送人若しくは荷受人の氏名又は 名称及び住所並びに当該核燃料物質等に係	輸送物に輸送計画書に記載されている荷送人若しくは荷受 人の氏名又は名称及び住所が表示されていることを目現確 認する。	食 · 否
该車両告示 第四条の二 第一項	る告示で定める国連番号「UN2915」が表示されていること。	輸送物に告示で定める国連番号「UN2915」が表示されている ことを目視確認する。	b 良·否
核車両規則 第九条 第二項 第二号 核車両告示 第四条の二 第二項	輸送物に当該核燃料物質等の告示で定める 品名が表示されていること。	輸送物に告示で定める品名「RADIOACTIVE MATERIAL, TYPE A PACKAGE」が表示されていることを目視確認する。	良・否
该車両規則 第九条 第二項 第四号	「A型」の文字又は「TYPE A」の文字が表示 されていること。	輸送物に「A型」の文字又は「TYPE A」の文字が表示されて いることを目視確認する。	: 良・否
该車両規則 第九条 第二項 第十号 该車両告示 第四条の二 第三項	TNB169容器は承認容器登録番号が定めら れていないため、輸送容器の設計された国の 名称及び製造業者名を表示していること。	輸送物に輸送容器の設計された国の名称及び製造業者名が 表示されていることを目視確認する。(TNB16)容器の場合に は設計された国の名称(BELGUIM)及び製造業社名 (TRANSNUBEL)を表示していること)	。 良・否
外運搬則 第五条 第一項 第九号	核燃料物質等の使用等に必要な書類その他 の物品(核燃料輸送物の安全性を損なうおそ れのないものに限る。)以外のものが収納さ れていないこと。	挿入し、笠属タクの上下の穴にシーリンクのワイヤーを通し、 シールを取り付けている、もしくは、蓋部のパックルの穴に直 - 捲シーリングのワイヤーを通し、シールを取り付けていること	
扑運搬則 第五条 第一項 第三号	輸送容器本体と蓋の間にシールが施されて いること。	を目視にて確認する。また、合わせて容弱外菌、蚕および パックルに傷・割れ等の被損および変形がないことを目視に て確認する。	0
	6'9~Ce	成田空港出発前に輸送物に追加したシール等の封印の措置 については1.もしくはシールが貼付けられていることを目視 確認する。	l 良·否
该車両規則 第九条 第一項 第一号~第三号 该車両告示 第四条 第一項 第一号~第三号	輸送物の表面最大線量当量率及び輸送指数 を確認すること。告示で定める標識を輸送物 の表面二箇所に貼付されていること。	告示で定める標識が輸送物の二箇所に貼付されていること。 目視で確認する。	• () · 否
毒劇法 第十二条 第一項	輸送物に「医薬用外劇物」の表示がされてい ること	輸送物に当地に赤色の文字で「医薬用外劇物」が表示されて いることを目視により確認する。	良・否
朴運搬則 第五条 第一項 第七号	表面における最大線量当量率が基準値を満 たすこと。 基準値:表面最大線量当量率<2mSv/h	日本原燃刷に輸送物を引き渡した後、日本原燃酸の放管員 は輸送物に対して純量当量率測定を実施する。TNTは測定	le)· 否
外運搬則 第五条 第一項 第八号	表面から1mはなれた場所における最大線量 当量率が基準値を満たすこと。 基準値:at 1m 最大線量当量率<100 μ Sv/r	結果を口頭にて間くことにより、線量当量率が法令の定める 基準値以下であることを確認する。	良・否
內運搬到 第五条 第一項 第一号 ⑥ 內運搬号 京為条 克運動 東京条 第八項) 京軍両規則 第十一条 第二項 京軍両告示 第九条 第一項 第一号	スミヤ 期定により、輸送物に対し以下の表面 密度限度を満たすこと。 表面密度限度: α <0.4 Bq/cm2、β γ <4 Bq/cm2	日本原単配に輸送物を引き流した後、日本原単原の放管員 は輸送物に対してスモヤ副定を発施する。FNFはスモヤ副定 結果を印刷にて間にことにより、法令の定める政密密度構度 以下であることを補握する。	良・香
		1	
第 [○] 2. 回目輸送	_	確認場所	フトトトーアの理コン
容器の型式: TNB 160		確認日	:2009年7月1日 22:00

Package and Vehicle
↓
No abnormal
↓
Delivery

Improvement

In order to carry out the transport of CRM efficiently, taking into account of the check for the conformity to transport regulation,

To decrease the number of package is one of way.

1) Excepted package or Type A package

The ready-made packaging is used.

This packaging isn't the one optimized for CRM

↓ The ready-made packaging will be modified to enlarge the capacity of CRM.

2) Type B package

The specific packaging will be designed for CRM to have the large capacity of CRM.

Packaging used for CRM — At present —



Packaging used for CRM — At present —



Open the lid of packaging



Take out inner can






Take off upper shock absorber



Composition of packaging

Package

– Improvement –



Package – Transport efficiency –

Inner space and inner can are enlarged. Amount of CRM in the packaging increases. Number of packaging decreases. Work for check decreases on the conformity to transport regulation.

The possibility of error will decreases.

on the conformity to transport regulation.

Conclusion

• Through the transport of CRM as Excepted package or Type A package with fissile-excepted,

We are studying the best transport mode, keeping transport regulation.

- We raise the improvement of the packaging. We introduce this leads to an efficient transport and decrease of error in check on the conformity to transport regulation.
- According to the amount of CRM demand, the type of package and transport mode has to be considered.